

Message Text

CONFIDENTIAL

PAGE 01 PANAMA 05246 211924Z
ACTION SY-05

INFO OCT-01 ARA-10 ISO-00 OC-06 CCO-00 /022 W
-----016477 221440Z /41

R 211922Z JUL 78
FM AMEMBASSY PANAMA
TO SECSTATE WASHDC 8076
INFO AMEMBASSY LIMA

C O N F I D E N T I A L PANAMA 05246

DEPT FOR A/SY/OPS/T, LIMA FOR RSO/ADM FROM RTC

E.O. 11652: GDS
TAGS: ASEC
SUBJECT: TECHNICAL SECURITY PROJECTS - LIMA

REF: STATE 182983

1. PARA 3: REMOVAL OF FOIL IMPOSSIBLE TASK. ALL WALLS COVERED WITH 1/2 INCH PLYWOOD WITH FOIL FIRMLY GLUED TO IT. RTC TEAM CAN REMOVE PANELS AND SHIP TO PANAMA FOR DISPOSAL.

2. PARA 4: REMOVAL OF FOIL IMPOSSIBLE. RTC TEAM CAN INSTALL NEW DROP CEILING IN ONE THIRD THE TIME THAT IT WOULD TAKE TO COVER THE OLD CEILING WITH CONTACT PAPER. A NEW CEILING WOULD BE PRESENTABLE. HOW LONG WOULD CONTACT PAPER REMAIN STUCK TO A FOIL CEILING? HOW CAN YOU GET A PROPER SMOOTH FINISH OVER THE ROUGH FOILING? IT MAY BE POSSIBLE, WITH SOLVENT AND SCRAPPERS, TO REMOVE MOST FOIL FROM THE FLOOR. THE POST COULD THEN LAY A RUG. WALLS MUST BE INSTALLED PRIOR TO INSTALLING CEILING OR LAYING RUG.

3. PARA 5: IS SY/T SAYING THAT RTC TEAM DO A COVER UP JOB, WHICH WOULD TAKE AS MUCH MANPOWER AND TIME AS A
CONFIDENTIAL

CONFIDENTIAL

PAGE 02 PANAMA 05246 211924Z

PROPER JOB, AND THEN HAVE THE POST DO THE FINISH JOB WITH RTC PROVIDING SECURITY SURVEILLANCE?

4. PARA 5B: POST HAS ALREADY HAD LOCAL CONTRACTOR INSTALL CEILING AS FAR AS POSSIBLE. SPACE DOES NOT PERMIT ANY FURTHER CEILING WORK BY LOCALS WITHOUT COMING IN CONTACT WITH TANK. POST COULD (WITH RESERVATIONS) HAVE

LOCAL CONTRACTOR DO SOME OF WALL PANELING.

5. SUGGEST SY/T RECONSIDER WHOSE RESPONSIBILITY IT IS TO
PERFORM PARA 5B, 1 & 2. RECOMMEND SY/T HOLD NEGATIVE
DECISION IN ABEYANCE UNTIL RECEIPT OF LIMA TSR OF 6 - 8
JULY 1978. JORDEN

CONFIDENTIAL

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 21 jul 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978PANAMA05246
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: GS
Errors: N/A
Expiration:
Film Number: D780302-0150
Format: TEL
From: PANAMA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780733/aaaabbzv.tel
Line Count: 68
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: b3e6146f-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: CONFIDENTIAL
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: n/a
Reference: 78 STATE 182983
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 20 jul 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1926525
Secure: OPEN
Status: NATIVE
Subject: TECHNICAL SECURITY PROJECTS - LIMA
TAGS: ASEC
To: STATE
Type: TE
vdkgvwkey: odbc://SAS/SAS.dbo.SAS_Docs/b3e6146f-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014